

Power

FULL STOP
... nothing else

PWR12



PWR07



PWR08



PT100



TEMPERATURE MONITORING UNIT

www.powerfullstop.com



More Power with **Power** FULL STOP
... nothing else

PWR07 - Temperature Relay for PT100 Sensors

- Supply: 24-240 V AC DC
- Input: 3-4 PT100 Sensors
- Output: 2 Alarm, 1 Fan, 1 Fault Relays
- Display: Temperature and channel
- Dimensions: L=96 mm, W=130 mm, H=96 mm

PWR08 - Temperature Relay for PTC Sensors

- Supply: 24-240 V AC DC
- Input: 3 PTC Sensors
- Output: 2 Alarm, 1 Fan Relays
- Dimensions: L=105 mm, W=73 mm, H=90 mm





PWR12 - Electric Motor Control

- Supply: 220-240 V AC
- Input: Remote Control Contact
- Output: 2 Ventilation Lines, 1 Fault Relay
- Dimensions: L=96 mm, W=130 mm, H=96 mm

PT100 Sensors

- Extension wire with 3 conductors
- Length: 2,5 m
- Pick-up Range: from -50°C up to +220°C
- Protection: IP68



Power

FULL
STOP

... nothing else

YOUR PARTNER FOR CAST RESIN TRANSFORMER



www.powerfullstop.com